

CLASSIFIED MESSAGE

SECRET

DATE 0725Z 23 APR 1963

1	0 FL	4	Commo
2	21	5	11
3	F PD	6	MD

TO : DIRECTOR

FROM : [redacted]

ACTION: OSA (1-15)

INFO : S/C (16)


Intit
DLP
D/tech
SD 50X1

PRIORITY 50X1

TOR: 0824Z 23 APR 1963

TO PRITY ADIC

INFO



CITE

[redacted] 50X1

HBJAYWALK ELINT

1. REQUEST [redacted] BE CONTACTED AND INSTRUCTED TO SHIP

INSTRUCTION BOOK COMPLETE WITH ALL INFO ON DIGITAL READOUT

BOARDS FOR [redacted] AIR MAILED ASAP. SPARE PARTS CONTAINED NO

REPEAT NO SPARE BOARDS FOR DIGITAL READOUT SECTION. NO SPARE

POWER SUPPLY PARTS. NEED FOLLOWING PLUG IN BOARDS TO COMPLETE

SPARE PARTS.

- | | | | |
|-------|---|--------|---|
| FF1-A | 2 | ST1 | 2 |
| FF1-B | 2 | GC-1B | 2 |
| PS2-A | 2 | FF1-C | 3 |
| PS1-A | 2 | GB17-A | 2 |
| ST1-B | 2 | 1A1-A | 2 |

DOCUMENT NO. _____
NO CHANGE IN CLASS. ☒
☐ DECLASSIFIED
CLASS. CHANGED TO: TS S G
NEXT REVIEW DATE: 2011
AUTH: HR 70-2
DATE: 15/9/01 REVIEWER: 064540

2. ALSO RECOMMEND THAT COMPONENTS OF POWER SUPPLY BE MOUNTED UPRIGHT. TWO MACHINES RECEIVED WITH TRANSFORMERS AND CHOKES BROKEN LOOSE. THESE WERE REPAIRED BUT FUTURE MANUFACTURE SHOULD TAKE INTO CONSIDERATION ROUGH SHIPMENT.

END OF MESSAGE

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification